



STEPS

(1) Hardware




(2) Printed Graphic Fabric Banner (Optional)




STEP 01

Interconnect aluminum profiles with built-in LED light stripes, connect adjacent LED light stripes with LED connectors.



STEP 02


Insert aluminum profiles without built-in LED light stripes onto feet.



STEPS


STEP 03

Interconnect aluminum profiles by pulling up buckle to insert into & pressing down to lock.



STEP 04


Insert support rods onto aluminum profiles with aligning their holes, interconnect upper & lower parts at sides.



STEPS


STEP 05

Interconnect support rods all around based on cross connectors & insert them onto aluminum profiles with aligning their holes.



STEP 06



Interconnect aluminum profiles by pulling up buckle to insert into & pressing down to lock, align support rods to their holes.



STEPS

STEP 07

Connect LED light stripes with jump wires out to switching power supplies either from left and/or right sides as needed.



STEP 08

Insert silicone edge graphic pieces into channels from corners. (Same Steps for Double Sides)

